

PART 573 Defect and Noncompliance Report

Indian Motorcycle Corporation, a California corporation ("IMC"), has determined that a defect which relates to motor vehicle safety exists in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports.

Date this report was prepared: March 31, 2003

Furnish the manufacturer's identification code for this recall (if applicable): NA

Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled.

Indian Motorcycle Corporation
200 E. Tenth Street
Gilroy, California 95020

Identify the corporate official, by name and title, whom the agency should contact with respect to this recall.

Andrew Broadley, Senior Director of Engineering

Telephone Number: 408-846-7257 **Fax No.:** 408-842-5612

Name and Title of Person who prepared this report.

Gabrielle Gallegos, General Counsel 408-846-7257

Signed:



Andrew Broadley, Senior Director of Engineering

RECEIVED
MAR - 4 A 9 40
OFFICE OF DEFECTS
INVESTIGATION

I. Identify the Vehicle Models Involved in the Recall

1.1 Identify the Vehicles Involved in the Recall, for each make and model or applicable vehicle line (provide illustrations or photographs as necessary to describe the vehicle), provide:

A. Make(s): IMC Model Years Involved: 2002 and 2003 Models: Scout and Spirit

Production Dates: Beginning: November 30, 2001 Ending: September 4, 2002

VIN Range: See attached list

Vehicle Type: Motorcycle Bodystyle: N/A

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

The vehicles included in the recall were manufactured with a shorter fuel tank vent tube than the vehicles manufactured after September 4, 2002.

1.2 Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above that the recalled model population represents.

100%

II. Identify the Recall Population

2.1 Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

1643

2.2 Model Year Potentially Involved

Largely 2002 with a few 2003

2.3 Total Number Potentially Affected by the Recall:

1643

2.4 Furnish the approximate percentage of the total number of vehicles estimated to actually contain the defect or noncompliance:

100%

2.5 Identify and describe how the recall population was determined—in particular how the recalled models were selected and the basis for the beginning and final dates of manufacture of the recalled vehicles:

The recall population includes all vehicles manufactured with vent tube part number 00-166 Rev A. Engineering made a running change in the configuration of this part and manufacturing implemented a revised version of this part on September 4, 2002.

III. Describe the Defect or Noncompliance

3.1 Describe the defect or noncompliance. The description should address the nature and physical location of the defect or noncompliance. Illustrations should be provided as appropriate.

The vent tube on the recalled vehicles is positioned on the underside of the frame such that the tube can become clogged with mud and debris kicked up by the front tire.

3.2 Describe the cause(s) of the defect or noncompliance condition.

The vent tube is poorly positioned.

3.3 Describe the consequence(s) of the defect or noncompliance condition.

The vent tube can become clogged. If the vent tube becomes completely blocked, fuel won't flow to the carburetor and the motorcycle will come to a stop. If the fuel tank is full and the bike is exposed to sufficient heat, the blockage could cause positive pressure to build up in the tank and force a small amount gas out through the fuel filler cap seal.

3.4 Identify any warning which can (a) precede or (b) occur.

If blockage is occurring, the bike will sputter and slowly come to a halt as the engine is deprived of fuel.

3.5 If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.

N/A

3.6 Identify the name and title of the chief executive officer or knowledgeable representative of the supplier.

N/A

IV. Provide the Chronology in Determining the Defect/Noncompliance

4.1 With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.

During 2002 IMC Field Service Managers occasionally heard reports of Scouts and Spirits losing consistent fuel flow to the carburetor, but they were never able to verify these reports or identify the cause. IMC engineering tried on repeated occasions to determine whether and under what conditions fuel flow could be interrupted. It was postulated that a clogged vent tube could cause this condition, but after repeated tests, IMC could not clog the vent tube by simply riding the motorcycle. However, IMC engineering determined that repositioning the vent tube would prevent any chance of clogging, and as this was an easy running change, IMC implemented this change in production in September of 2002.

After September, IMC engineering continued to try to determine the possible sources of interrupted fuel flow. IMC experimented by purposefully closing off the vent tube. IMC also continued road tests with this condition in mind. IMC finally encountered this condition by chance during a recent rainy spell when a bike being ridden by a test rider on a muddy dirt road experienced interrupted fuel flow due to a clogged vent tube. Upon consideration, IMC decided to issue a recall. IMC has had no reports of injuries or fatalities due to clogged vent tubes.

V. Identify the Remedy

5.1 Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

The remedy for vent tube clogging is to change the position of the vent tube on the bike. The new tube is longer and positioned further back on the frame where it is protected from debris kicked up by the front tire. See the attached Service Bulletin for a complete description of the repositioning of the vent tube.

5.2 Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

See 5.1

5.3 Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

The recall condition was corrected in production on September 4, 2002. The production remedy is the same as the recall remedy.

VI. Identify the Recall Schedule

6.1 Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.

Notification Schedule

April 14, 2003: Notification to dealers

In April upon approval of consumer letter by NHSTA: Notification to consumers.

Remedy Schedule

IMC has the replacement parts in stock and will ship them to dealers upon request.

VII. Furnish Recall Communications

7.1 Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification. A DRAFT copy of the notification documents should be submitted to this office by Fax (202-366-7882) for review prior to mailing.

The following documents are attached:

- 1) Draft of notification letter to consumers.

Service Bulletin will be sent as soon as it's completed.

Spirit 2002	SCDM5B5132G004269	SCDM5B5172G004369	SCDM5B5172G004419	SCDM5B5182G004493	SCDM5B5132G004563
SCDM5B5182G004011	SCDM5B51D2G004270	SCDM5B5132G004370	SCDM5B5132G004420	SCDM5B51X2G004494	SCDM5B5142G004801
SCDM5B51X2G004012	SCDM5B5112G004271	SCDM5B5152G004371	SCDM5B5152G004421	SCDM5B5112G004495	SCDM5B5162G004802
SCDM5B5112G004013	SCDM5B5132G004272	SCDM5B5172G004372	SCDM5B5172G004422	SCDM5B5132G004496	SCDM5B5182G004803
SCDM5B5132G004014	SCDM5B5152G004273	SCDM5B5192G004373	SCDM5B5192G004423	SCDM5B5152G004497	SCDM5B5132G004804
SCDM5B5132G004015	SCDM5B5172G004274	SCDM5B5102G004374	SCDM5B5102G004424	SCDM5B5172G004498	SCDM5B5132G004805
SCDM5B5172G004016	SCDM5B5192G004275	SCDM5B5122G004375	SCDM5B5122G004425	SCDM5B5112G004500	SCDM5B5152G004807
SCDM5B5192G004017	SCDM5B5102G004276	SCDM5B5142G004376	SCDM5B5142G004426	SCDM5B5132G004501	SCDM5B5172G004808
SCDM5B5102G004018	SCDM5B5122G004277	SCDM5B5162G004377	SCDM5B5162G004427	SCDM5B5152G004502	SCDM5B5192G004809
SCDM5B5122G004019	SCDM5B5142G004278	SCDM5B5162G004378	SCDM5B5182G004428	SCDM5B5172G004503	SCDM5B5152G004810
SCDM5B5192G004020	SCDM5B5152G004279	SCDM5B51X2G004379	SCDM5B51X2G004429	SCDM5B5192G004504	SCDM5B5172G004811
SCDM5B5102G004102	SCDM5B5122G004280	SCDM5B5162G004380	SCDM5B5162G004430	SCDM5B5102G004505	SCDM5B5192G004812
SCDM5B5102G004231	SCDM5B5142G004281	SCDM5B5162G004381	SCDM5B5182G004431	SCDM5B5142G004507	SCDM5B5162G004813
SCDM5B5122G004232	SCDM5B5162G004282	SCDM5B51X2G004382	SCDM5B51X2G004432	SCDM5B5162G004508	SCDM5B5122G004814
SCDM5B5142G004233	SCDM5B5182G004283	SCDM5B5112G004383	SCDM5B5112G004433	SCDM5B5182G004509	SCDM5B5142G004815
SCDM5B5162G004234	SCDM5B51X2G004284	SCDM5B5132G004384	SCDM5B5132G004434	SCDM5B5142G004510	SCDM5B5182G004817
SCDM5B5182G004235	SCDM5B5112G004285	SCDM5B5152G004385	SCDM5B5152G004435	SCDM5B5162G004511	SCDM5B51X2G004818
SCDM5B51X2G004236	SCDM5B5132G004286	SCDM5B5172G004386	SCDM5B5172G004436	SCDM5B5182G004512	SCDM5B5112G004819
SCDM5B5112G004237	SCDM5B5152G004287	SCDM5B5192G004387	SCDM5B5192G004437	SCDM5B51X2G004513	SCDM5B5182G004820
SCDM5B5132G004238	SCDM5B5172G004288	SCDM5B5102G004388	SCDM5B5102G004438	SCDM5B5112G004514	SCDM5B51X2G004821
SCDM5B5152G004239	SCDM5B5192G004289	SCDM5B5122G004389	SCDM5B5122G004439	SCDM5B5132G004515	SCDM5B5132G004823
SCDM5B5112G004240	SCDM5B5152G004290	SCDM5B5192G004390	SCDM5B5192G004440	SCDM5B5152G004516	SCDM5B5152G004824
SCDM5B5132G004241	SCDM5B5172G004291	SCDM5B5102G004391	SCDM5B5102G004441	SCDM5B5172G004517	SCDM5B5172G004825
SCDM5B5152G004242	SCDM5B5192G004292	SCDM5B5122G004392	SCDM5B5122G004442	SCDM5B5192G004518	SCDM5B5192G004826
SCDM5B5172G004243	SCDM5B5102G004293	SCDM5B5142G004393	SCDM5B5142G004443	SCDM5B5102G004519	SCDM5B5102G004827
SCDM5B5192G004244	SCDM5B5122G004294	SCDM5B5162G004394	SCDM5B5112G004450	SCDM5B5172G004520	SCDM5B5122G004828
SCDM5B5102G004245	SCDM5B5142G004295	SCDM5B5182G004395	SCDM5B5132G004451	SCDM5B5192G004521	SCDM5B5142G004829
SCDM5B5122G004246	SCDM5B5162G004296	SCDM5B51X2G004396	SCDM5B5152G004452	SCDM5B5102G004522	SCDM5B5102G004830
SCDM5B5142G004247	SCDM5B5182G004297	SCDM5B5112G004397	SCDM5B5172G004453	SCDM5B5122G004523	SCDM5B5122G004831
SCDM5B5162G004248	SCDM5B51X2G004298	SCDM5B5132G004398	SCDM5B5192G004454	SCDM5B5142G004524	SCDM5B5142G004832
SCDM5B5182G004249	SCDM5B5112G004299	SCDM5B5152G004399	SCDM5B5102G004455	SCDM5B5152G004525	SCDM5B5162G004833
SCDM5B5142G004250	SCDM5B5142G004300	SCDM5B5182G004400	SCDM5B5122G004456	SCDM5B5182G004526	SCDM5B5182G004834
SCDM5B5182G004251	SCDM5B5132G004351	SCDM5B51X2G004401	SCDM5B5142G004457	SCDM5B5112G004527	SCDM5B5152G004838
SCDM5B5182G004252	SCDM5B5112G004352	SCDM5B5112G004402	SCDM5B5162G004458	SCDM5B5112G004528	SCDM5B5172G004839
SCDM5B5132G004253	SCDM5B5132G004353	SCDM5B5132G004403	SCDM5B5182G004459	SCDM5B5132G004529	SCDM5B5152G004841
SCDM5B5112G004254	SCDM5B5152G004354	SCDM5B5152G004404	SCDM5B5142G004460	SCDM5B51X2G004530	SCDM5B5192G004843
SCDM5B5132G004255	SCDM5B5172G004355	SCDM5B5172G004405	SCDM5B5152G004461	SCDM5B5112G004531	SCDM5B5102G004844
SCDM5B5152G004256	SCDM5B5182G004356	SCDM5B5192G004406	SCDM5B5182G004462	SCDM5B5192G004532	SCDM5B5122G004845
SCDM5B5172G004257	SCDM5B5102G004357	SCDM5B5102G004407	SCDM5B51X2G004463	SCDM5B5152G004533	SCDM5B5142G004846
SCDM5B5192G004258	SCDM5B5122G004358	SCDM5B5122G004408	SCDM5B5112G004464	SCDM5B5172G004534	SCDM5B51X2G004849
SCDM5B5102G004259	SCDM5B5142G004359	SCDM5B5142G004409	SCDM5B5132G004465	SCDM5B5192G004535	SCDM5B5162G004850
SCDM5B5172G004260	SCDM5B5102G004360	SCDM5B5102G004410	SCDM5B5L52G004466	SCDM5B5102G004536	SCDM5B5132G004854
SCDM5B5192G004261	SCDM5B5122G004361	SCDM5B5122G004411	SCDM5B5172G004467	SCDM5B5122G004537	SCDM5B5152G004855
SCDM5B5102G004262	SCDM5B5142G004362	SCDM5B5142G004412	SCDM5B5192G004468	SCDM5B5122G004540	SCDM5B5172G004856
SCDM5B5122G004263	SCDM5B5162G004363	SCDM5B5162G004413	SCDM5B5102G004469	SCDM5B5142G004541	SCDM5B5192G004857
SCDM5B5142G004264	SCDM5B5182G004364	SCDM5B5182G004414	SCDM5B5172G004470	SCDM5B5162G004542	SCDM5B5102G004858
SCDM5B5162G004265	SCDM5B51X2G004365	SCDM5B51X2G004415	SCDM5B5142G004488	SCDM5B5182G004543	SCDM5B5122G004859
SCDM5B5182G004266	SCDM5B5112G004366	SCDM5B5112G004416	SCDM5B5162G004489	SCDM5B51X2G004544	SCDM5B5192G004860
SCDM5B51X2G004267	SCDM5B5132G004367	SCDM5B5132G004417	SCDM5B5122G004490	SCDM5B5172G004548	SCDM5B5102G004861
SCDM5B5112G004268	SCDM5B5152G004368	SCDM5B5152G004418	SCDM5B5162G004492	SCDM5B5192G004549	SCDM5B5122G004862

SCDM5B5142G004863	SCDM5B5152G004922	SCDM5B5192G004972	SCDM5B5192G005328	SCDM5B5132G005387	SCDM5B5182G005448
SCDM5B5132G004868	SCDM5B5172G004923	SCDM5B5102G004973	SCDM5B5192G005331	SCDM5B5152G005388	SCDM5B51X2G005449
SCDM5B5152G004869	SCDM5B5192G004924	SCDM5B5122G004974	SCDM5B5102G005332	SCDM5B5172G005389	SCDM5B5162G005450
SCDM5B5112G004870	SCDM5B5102G004925	SCDM5B5142G004975	SCDM5B5122G005333	SCDM5B5132G005390	SCDM5B5182G005451
SCDM5B5132G004871	SCDM5B5122G004926	SCDM5B5182G004977	SCDM5B5142G005334	SCDM5B5152G005391	SCDM5B51X2G005452
SCDM5B5152G004872	SCDM5B5142G004927	SCDM5B51X2G004978	SCDM5B5162G005335	SCDM5B5172G005392	SCDM5B5112G005453
SCDM5B5172G004873	SCDM5B5162G004929	SCDM5B5112G004979	SCDM5B5182G005336	SCDM5B5192G005393	SCDM5B5132G005454
SCDM5B5102G004875	SCDM5B5162G004929	SCDM5B5182G004980	SCDM5B51X2G005337	SCDM5B5102G005394	SCDM5B5152G005455
SCDM5B5122G004876	SCDM5B5142G004930	SCDM5B51X2G004981	SCDM5B5112G005338	SCDM5B5122G005395	SCDM5B5122G005459
SCDM5B5142G004877	SCDM5B5162G004931	SCDM5B5112G004982	SCDM5B5132G005339	SCDM5B5142G005396	SCDM5B5192G005460
SCDM5B5162G004878	SCDM5B5182G004932	SCDM5B5132G004983	SCDM5B51X2G005340	SCDM5B5152G005397	SCDM5B5102G005461
SCDM5B5182G004879	SCDM5B51X2G004933	SCDM5B5152G004984	SCDM5B5132G005342	SCDM5B51X2G005399	SCDM5B5122G005462
SCDM5B5142G004880	SCDM5B5112G004934	SCDM5B5172G004985	SCDM5B5152G005343	SCDM5B5122G005460	SCDM5B5142G005463
SCDM5B5162G004881	SCDM5B5132G004935	SCDM5B5142G004989	SCDM5B5172G005344	SCDM5B5142G005401	SCDM5B5162G005464
SCDM5B5182G004882	SCDM5B5152G004936	SCDM5B5102G004989	SCDM5B5192G005345	SCDM5B5162G005402	SCDM5B5182G005465
SCDM5B5132G004885	SCDM5B5172G004937	SCDM5B5142G004992	SCDM5B5102G005346	SCDM5B5182G005403	SCDM5B51X2G005466
SCDM5B5152G004886	SCDM5B5192G004938	SCDM5B5182G004993	SCDM5B5122G005347	SCDM5B5152G005410	SCDM5B5132G005471
SCDM5B5172G004887	SCDM5B5102G004939	SCDM5B5182G004994	SCDM5B5142G005348	SCDM5B5172G005411	SCDM5B5152G005472
SCDM5B5172G004890	SCDM5B5172G004940	SCDM5B51X2G004995	SCDM5B5162G005349	SCDM5B5192G005412	SCDM5B5172G005479
SCDM5B5192G004891	SCDM5B5192G004941	SCDM5B5112G004996	SCDM5B5122G005350	SCDM5B5102G005413	SCDM5B5192G005474
SCDM5B5102G004992	SCDM5B5102G004942	SCDM5B5132G004997	SCDM5B5142G005351	SCDM5B5122G005414	SCDM5B5102G005475
SCDM5B5122G004993	SCDM5B5122G004943	SCDM5B5152G004998	SCDM5B5162G005352	SCDM5B5142G005415	SCDM5B5122G005476
SCDM5B5142G004994	SCDM5B5142G004944	SCDM5B5172G004999	SCDM5B51X2G005354	SCDM5B5162G005416	SCDM5B5142G005477
SCDM5B5182G004995	SCDM5B5182G004945	SCDM5B5182G005000	SCDM5B5112G005355	SCDM5B5182G005417	SCDM5B5182G005478
SCDM5B5182G004996	SCDM5B5182G004946	SCDM5B5102G005301	SCDM5B5132G005356	SCDM5B51X2G005418	SCDM5B5182G005479
SCDM5B51X2G004997	SCDM5B51X2G004947	SCDM5B5122G005302	SCDM5B5152G005357	SCDM5B5132G005423	SCDM5B5142G005480
SCDM5B5112G004998	SCDM5B5112G004948	SCDM5B5142G005303	SCDM5B5172G005358	SCDM5B5152G005424	SCDM5B5162G005481
SCDM5B5132G004999	SCDM5B5132G004949	SCDM5B5162G005304	SCDM5B5192G005359	SCDM5B5172G005425	SCDM5B5182G005482
SCDM5B5162G004900	SCDM5B51X2G004950	SCDM5B5182G005305	SCDM5B5152G005360	SCDM5B5192G005426	SCDM5B51X2G005483
SCDM5B5182G004901	SCDM5B5112G004951	SCDM5B51X2G005306	SCDM5B5172G005361	SCDM5B5102G005427	SCDM5B5112G005484
SCDM5B51X2G004902	SCDM5B5132G004952	SCDM5B5112G005307	SCDM5B5192G005362	SCDM5B5122G005428	SCDM5B5132G005485
SCDM5B5112G004903	SCDM5B5152G004953	SCDM5B5132G005308	SCDM5B5102G005363	SCDM5B5142G005429	SCDM5B5152G005486
SCDM5B5132G004904	SCDM5B5172G004954	SCDM5B5152G005308	SCDM5B5122G005364	SCDM5B5102G005430	SCDM5B5172G005487
SCDM5B5152G004905	SCDM5B5192G004955	SCDM5B5112G005310	SCDM5B51X2G005368	SCDM5B5122G005431	SCDM5B5192G005488
SCDM5B5172G004906	SCDM5B5102G004956	SCDM5B5132G005311	SCDM5B51X2G005371	SCDM5B5142G005432	SCDM5B5102G005489
SCDM5B5192G004907	SCDM5B5122G004957	SCDM5B5152G005312	SCDM5B5112G005372	SCDM5B5152G005433	SCDM5B5192G005491
SCDM5B5102G004908	SCDM5B5142G004958	SCDM5B5172G005313	SCDM5B5132G005373	SCDM5B5182G005434	SCDM5B5102G005492
SCDM5B5122G004909	SCDM5B5162G004959	SCDM5B5192G005314	SCDM5B5152G005374	SCDM5B51X2G005435	SCDM5B5122G005493
SCDM5B5192G004910	SCDM5B5122G004960	SCDM5B5102G005315	SCDM5B5172G005375	SCDM5B5112G005436	SCDM5B5142G005494
SCDM5B5102G004911	SCDM5B5142G004961	SCDM5B5122G005316	SCDM5B5192G005376	SCDM5B5132G005437	SCDM5B5162G005495
SCDM5B5122G004912	SCDM5B5162G004962	SCDM5B5142G005317	SCDM5B5102G005377	SCDM5B5152G005438	SCDM5B5182G005496
SCDM5B5142G004913	SCDM5B5182G004963	SCDM5B5162G005318	SCDM5B5122G005378	SCDM5B5172G005439	SCDM5B51X2G005497
SCDM5B5162G004914	SCDM5B51X2G004964	SCDM5B5182G005319	SCDM5B5142G005379	SCDM5B5132G005440	SCDM5B5112G005498
SCDM5B5182G004915	SCDM5B5112G004965	SCDM5B5142G005320	SCDM5B5102G005380	SCDM5B5152G005441	SCDM5B5132G005499
SCDM5B51X2G004916	SCDM5B5132G004966	SCDM5B5162G005321	SCDM5B5122G005381	SCDM5B5172G005442	SCDM5B5162G005500
SCDM5B5112G004917	SCDM5B5152G004957	SCDM5B5182G005322	SCDM5B5142G005382	SCDM5B5182G005443	SCDM5B5162G007201
SCDM5B5132G004918	SCDM5B5172G004958	SCDM5B51X2G005323	SCDM5B5162G005383	SCDM5B5102G005444	SCDM5B5182G007202
SCDM5B5152G004919	SCDM5B5192G004969	SCDM5B5112G005324	SCDM5B5182G005384	SCDM5B5122G005445	SCDM5B5192G007203
SCDM5B5112G004920	SCDM5B5152G004970	SCDM5B5132G005325	SCDM5B51X2G005385	SCDM5B5142G005446	SCDM5B5112G007204
SCDM5B5132G004921	SCDM5B5172G004971	SCDM5B5172G005327	SCDM5B5112G005386	SCDM5B5162G005447	SCDM5B5132G007205

SCDM5B5192G007204	SCDM5B5162G007263	SCDM5B5152G007321	SCDM5B5142G007391	SCDMTB5152G004151	SCDMTB5192G004203
SCDM5B5102G007205	SCDM5B5152G007264	SCDM5B5172G007322	SCDM5B5162G007392	SCDMTB5172G004152	SCDMTB5102G004204
SCDM5B5172G007210	SCDM5B51X2G007265	SCDM5B5192G007323	SCDM5B5182G007393	SCDMTB5192G004153	SCDMTB5122G004205
SCDM5B5192G007211	SCDM5B5112G007266	SCDM5B5102G007324	SCDM5B51X2G007394	SCDMTB5102G004154	SCDMTB5142G004206
SCDM5B5102G007212	SCDM5B5132G007267	SCDM5B5122G007325	SCDM5B5112G007395	SCDMTB5122G004155	SCDMTB5162G004207
SCDM5B5122G007213	SCDM5B5152G007268	SCDM5B5142G007326	SCDM5B5132G007396	SCDMTB5142G004156	SCDMTB5182G004208
SCDM5B5142G007214	SCDM5B5172G007269	SCDM5B5162G007327	SCDM5B5132G007396	SCDMTB5162G004157	SCDMTB51X2G004209
SCDM5B5162G007215	SCDM5B5132G007270	SCDM5B5182G007328	SCDM5B5182G004222	SCDMTB5182G004158	SCDMTB5162G004210
SCDM5B5182G007216	SCDM5B5152G007271	SCDM5B51X2G007329	SCDM5B51X2G004223	SCDMTB51X2G004159	SCDMTB5182G004211
SCDM5B51X2G007217	SCDM5B5172G007272	SCDM5B5162G007330	SCDM5B5112G008224	SCDMTB5162G004160	SCDMTB51X2G004212
SCDM5B5112G007218	SCDM5B5192G007273	SCDM5B5182G007331	SCDM5B5132G008225	SCDMTB5182G004151	SCDMTB5112G004213
SCDM5B5132G007219	SCDM5B5102G007224	SCDM5B51X2G007332	SCDM5B5152G008226	SCDMTB51X2G004152	SCDMTB5132G004214
SCDM5B51X2G007220	SCDM5B5122G007275	SCDM5B5112G007333	SCDM5B5172G008227	SCDMTB5112G004163	SCDMTB5152G004215
SCDM5B5112G007221	SCDM5B5162G007277	SCDM5B5132G007334	SCDM5B5192G008228	SCDMTB5132G004154	SCDMTB5172G004216
SCDM5B5132G007222	SCDM5B5162G007278	SCDM5B5112G007335	SCDM5B5112G008229	SCDMTB5152G004165	SCDMTB5192G004217
SCDM5B5152G007223	SCDM5B5172G007286	SCDM5B5172G007336	SCDM5B5172G008230	SCDMTB5172G004166	SCDMTB5102G004218
SCDM5B5172G007224	SCDM5B5192G007287	SCDM5B5192G007337	SCDM5B5192G008231	SCDMTB5192G004167	SCDMTB5122G004219
SCDM5B5192G007225	SCDM5B5102G007288	SCDM5B5192G007340	SCDM5B5102G008232	SCDMTB5102G004168	SCDMTB5192G004220
SCDM5B5102G007226	SCDM5B5122G007289	SCDM5B5102G007341	SCDM5B5122G008233	SCDMTB5122G004169	SCDMTB5102G004221
SCDM5B5122G007227	SCDM5B5192G007290	SCDM5B5122G007342	SCDM5B5142G008234	SCDMTB5192G004170	SCDMTB5122G004222
SCDM5B5142G007228	SCDM5B5102G007291	SCDM5B5142G007343	SCDM5B5162G008235	SCDMTB5102G004171	SCDMTB5142G004223
SCDM5B5162G007229	SCDM5B5122G007292	SCDM5B5162G007344	SCDM5B5182G008236	SCDMTB5122G004172	SCDMTB5162G004224
SCDM5B5122G007230	SCDM5B5142G007293	SCDM5B5182G007345	SCDM5B51X2G008237	SCDMTB5142G004173	SCDMTB5182G004225
SCDM5B5142G007231	SCDM5B5162G007294	SCDM5B51X2G007346	Scout 2002	SCDMTB5162G004174	SCDMTB5192G004301
SCDM5B5162G007232	SCDM5B5182G007295	SCDM5B5112G007347	SCDMTB5142G004125	SCDMTB5182G004175	SCDMTB5102G004302
SCDM5B5182G007233	SCDM5B51X2G007296	SCDM5B5112G007350	SCDMTB5162G004126	SCDMTB51X2G004176	SCDMTB5122G004303
SCDM5B51X2G007234	SCDM5B5112G007297	SCDM5B5112G007351	SCDMTB5182G004127	SCDMTB5112G004177	SCDMTB5142G004304
SCDM5B5112G007235	SCDM5B5132G007298	SCDM5B5152G007352	SCDMTB51X2G004128	SCDMTB5132G004178	SCDMTB5162G004305
SCDM5B5132G007236	SCDM5B5152G007299	SCDM5B5172G007353	SCDMTB5112G004129	SCDMTB5152G004179	SCDMTB5182G004306
SCDM5B5152G007237	SCDM5B5182G007300	SCDM5B5182G007358	SCDMTB5182G004130	SCDMTB5112G004180	SCDMTB51X2G004307
SCDM5B5172G007238	SCDM5B51X2G007301	SCDM5B5182G007359	SCDMTB51X2G004131	SCDMTB5132G004181	SCDMTB5112G004308
SCDM5B5192G007239	SCDM5B5112G007302	SCDM5B5142G007360	SCDMTB5112G004132	SCDMTB5152G004182	SCDMTB5132G004309
SCDM5B5152G007240	SCDM5B5132G007303	SCDM5B5162G007361	SCDMTB5132G004133	SCDMTB5172G004183	SCDMTB5192G004310
SCDM5B5172G007241	SCDM5B5152G007304	SCDM5B5162G007362	SCDMTB5152G004134	SCDMTB5192G004184	SCDMTB5112G004311
SCDM5B5192G007242	SCDM5B5172G007305	SCDM5B5152G007364	SCDMTB5172G004135	SCDMTB5102G004185	SCDMTB5132G004312
SCDM5B5102G007243	SCDM5B5192G007306	SCDM5B5172G007367	SCDMTB5192G004136	SCDMTB5122G004186	SCDMTB5152G004313
SCDM5B5122G007244	SCDM5B5102G007307	SCDM5B5152G007368	SCDMTB5102G004137	SCDMTB5142G004187	SCDMTB5172G004314
SCDM5B5142G007245	SCDM5B5122G007308	SCDM5B5172G007370	SCDMTB5122G004138	SCDMTB5162G004188	SCDMTB5192G004315
SCDM5B5162G007246	SCDM5B5142G007309	SCDM5B5192G007371	SCDMTB5142G004139	SCDMTB5182G004189	SCDMTB5102G004316
SCDM5B5182G007247	SCDM5B5102G007310	SCDM5B5102G007372	SCDMTB5102G004140	SCDMTB5142G004190	SCDMTB5122G004317
SCDM5B51X2G007251	SCDM5B5122G007311	SCDM5B5122G007373	SCDMTB5122G004141	SCDMTB5162G004191	SCDMTB5142G004318
SCDM5B5112G007252	SCDM5B5142G007312	SCDM5B5142G007374	SCDMTB5142G004142	SCDMTB5182G004192	SCDMTB5162G004319
SCDM5B5132G007253	SCDM5B5162G007313	SCDM5B5162G007375	SCDMTB5162G004143	SCDMTB51X2G004193	SCDMTB5122G004320
SCDM5B5152G007254	SCDM5B5182G007314	SCDM5B5182G007376	SCDMTB5112G004144	SCDMTB5112G004194	SCDMTB5142G004321
SCDM5B5172G007255	SCDM5B51X2G007315	SCDM5B51X2G007377	SCDMTB51X2G004145	SCDMTB5132G004195	SCDMTB5152G004322
SCDM5B5192G007256	SCDM5B5112G007316	SCDM5B5112G007378	SCDMTB5112G004146	SCDMTB5152G004196	SCDMTB5182G004323
SCDM5B5102G007257	SCDM5B5132G007317	SCDM5B5132G007379	SCDMTB5132G004147	SCDMTB5172G004197	SCDMTB51X2G004324
SCDM5B5122G007258	SCDM5B5152G007318	SCDM5B5152G007380	SCDMTB5152G004148	SCDMTB5192G004198	SCDMTB5112G004325
SCDM5B5122G007261	SCDM5B5172G007319	SCDM5B5142G007386	SCDMTB5172G004149	SCDMTB5162G004199	SCDMTB5132G004326
SCDM5B5142G007262	SCDM5B5132G007320	SCDM5B5122G007390	SCDMTB5132G004150	SCDMTB5132G004200	SCDMTB5152G004327

SCDMTB5172G004328	SCDMTB51X2G004579	SCDMTB51X2G004629	SCDMTB5152G004696	SCDMTB5152G004747	SCDMTB5182G005021
SCDMTB5192G004329	SCDMTB5162G004580	SCDMTB5162G004630	SCDMTB5152G004697	SCDMTB5172G004748	SCDMTB51X2G005022
SCDMTB5152G004330	SCDMTB5182G004581	SCDMTB5182G004631	SCDMTB5172G004698	SCDMTB5192G004749	SCDMTB5112G005023
SCDMTB5172G004331	SCDMTB51X2G004582	SCDMTB51X2G004632	SCDMTB5192G004699	SCDMTB5152G004750	SCDMTB5132G005024
SCDMTB5192G004332	SCDMTB5112G004583	SCDMTB5112G004633	SCDMTB5112G004700	SCDMTB5172G004751	SCDMTB5172G005025
SCDMTB5102G004333	SCDMTB5132G004584	SCDMTB5132G004634	SCDMTB5132G004701	SCDMTB5192G004752	SCDMTB5192G005027
SCDMTB5122G004334	SCDMTB5152G004585	SCDMTB5152G004635	SCDMTB5152G004702	SCDMTB5102G004753	SCDMTB5102G005028
SCDMTB5142G004335	SCDMTB5172G004586	SCDMTB5172G004636	SCDMTB5172G004703	SCDMTB5122G004754	SCDMTB5122G005029
SCDMTB5162G004336	SCDMTB5192G004587	SCDMTB5192G004637	SCDMTB5192G004704	SCDMTB5142G004755	SCDMTB5192G005030
SCDMTB5182G004337	SCDMTB5102G004588	SCDMTB5102G004638	SCDMTB5102G004705	SCDMTB5162G004756	SCDMTB5102G005031
SCDMTB51X2G004338	SCDMTB5122G004589	SCDMTB5122G004639	SCDMTB5122G004706	SCDMTB5182G004757	SCDMTB5142G005033
SCDMTB5112G004339	SCDMTB5192G004590	SCDMTB5192G004640	SCDMTB5142G004707	SCDMTB51X2G004758	SCDMTB5162G005034
SCDMTB5182G004340	SCDMTB5102G004591	SCDMTB5102G004641	SCDMTB5162G004708	SCDMTB5132G004777	SCDMTB5182G005035
SCDMTB51X2G004341	SCDMTB5122G004592	SCDMTB5122G004642	SCDMTB5182G004709	SCDMTB5152G004778	SCDMTB51X2G005036
SCDMTB5112G004342	SCDMTB5142G004593	SCDMTB5142G004643	SCDMTB5142G004710	SCDMTB5172G004779	SCDMTB5112G005037
SCDMTB5132G004343	SCDMTB5162G004594	SCDMTB5162G004644	SCDMTB5162G004711	SCDMTB5132G004780	SCDMTB5132G005038
SCDMTB5152G004344	SCDMTB5182G004595	SCDMTB5182G004645	SCDMTB51X2G004713	SCDMTB5122G004785	SCDMTB5112G005040
SCDMTB5172G004345	SCDMTB51X2G004596	SCDMTB51X2G004646	SCDMTB5112G004714	SCDMTB5142G004786	SCDMTB5152G005042
SCDMTB5192G004346	SCDMTB5112G004597	SCDMTB5112G004647	SCDMTB5132G004715	SCDMTB5162G004787	SCDMTB5172G005043
SCDMTB5102G004347	SCDMTB5132G004598	SCDMTB5132G004648	SCDMTB5152G004716	SCDMTB5182G004788	SCDMTB5192G005044
SCDMTB5122G004348	SCDMTB5152G004599	SCDMTB5152G004649	SCDMTB5172G004717	SCDMTB51X2G004789	SCDMTB5102G005045
SCDMTB5142G004349	SCDMTB5182G004600	SCDMTB5122G004650	SCDMTB5192G004718	SCDMTB51X2G004792	SCDMTB5122G005046
SCDMTB5102G004350	SCDMTB51X2G004601	SCDMTB5132G004651	SCDMTB5102G004719	SCDMTB5112G004793	SCDMTB5162G005048
SCDMTB51X2G004551	SCDMTB5112G004602	SCDMTB5152G004652	SCDMTB5172G004720	SCDMTB5132G004794	SCDMTB5182G005049
SCDMTB5112G004552	SCDMTB5132G004603	SCDMTB5172G004653	SCDMTB5192G004721	SCDMTB5152G004795	SCDMTB5142G005050
SCDMTB5132G004553	SCDMTB5152G004604	SCDMTB5192G004654	SCDMTB5102G004722	SCDMTB5192G004797	SCDMTB5122G005053
SCDMTB5152G004554	SCDMTB5172G004605	SCDMTB5102G004655	SCDMTB5122G004723	SCDMTB5102G004798	SCDMTB5132G005054
SCDMTB5172G004555	SCDMTB5192G004606	SCDMTB5122G004656	SCDMTB5142G004724	SCDMTB5122G004799	SCDMTB5152G005056
SCDMTB5192G004556	SCDMTB5102G004607	SCDMTB5142G004657	SCDMTB5162G004725	SCDMTB5152G004800	SCDMTB5172G005057
SCDMTB5102G004557	SCDMTB5122G004608	SCDMTB5162G004658	SCDMTB5182G004726	SCDMTB5142G004805	SCDMTB5192G005058
SCDMTB5122G004558	SCDMTB5142G004609	SCDMTB5182G004659	SCDMTB51X2G004727	SCDMTB5122G005001	SCDMTB5172G005060
SCDMTB5142G004559	SCDMTB5102G004610	SCDMTB5142G004660	SCDMTB5112G004728	SCDMTB5142G005002	SCDMTB5192G005061
SCDMTB5102G004560	SCDMTB5122G004611	SCDMTB5162G004661	SCDMTB5132G004729	SCDMTB5112G005003	SCDMTB5102G005062
SCDMTB5122G004561	SCDMTB5142G004612	SCDMTB5182G004662	SCDMTB51X2G004730	SCDMTB5182G005004	SCDMTB5182G005063
SCDMTB5142G004562	SCDMTB5162G004613	SCDMTB51X2G004663	SCDMTB5112G004731	SCDMTB51X2G005005	SCDMTB5182G005066
SCDMTB5182G004564	SCDMTB5182G004614	SCDMTB5112G004664	SCDMTB5132G004732	SCDMTB5112G005006	SCDMTB51X2G005067
SCDMTB51X2G004565	SCDMTB51X2G004615	SCDMTB5132G004665	SCDMTB5152G004733	SCDMTB5132G005007	SCDMTB5112G005068
SCDMTB5112G004566	SCDMTB5112G004616	SCDMTB5152G004666	SCDMTB5172G004734	SCDMTB5152G005008	SCDMTB5132G005069
SCDMTB5132G004567	SCDMTB5132G004617	SCDMTB5172G004667	SCDMTB5192G004735	SCDMTB5172G005009	SCDMTB51X2G005070
SCDMTB5152G004568	SCDMTB5152G004618	SCDMTB5192G004668	SCDMTB5102G004736	SCDMTB5132G005010	SCDMTB5112G005071
SCDMTB5172G004569	SCDMTB5172G004619	SCDMTB5102G004669	SCDMTB5122G004737	SCDMTB5152G005011	SCDMTB5152G005073
SCDMTB5132G004570	SCDMTB5132G004620	SCDMTB5172G004670	SCDMTB5142G004738	SCDMTB5172G005012	SCDMTB5172G005074
SCDMTB5152G004571	SCDMTB5152G004621	SCDMTB5192G004671	SCDMTB5162G004739	SCDMTB5192G005013	SCDMTB5192G005075
SCDMTB5172G004572	SCDMTB5172G004622	SCDMTB5102G004672	SCDMTB5182G004740	SCDMTB5102G005014	SCDMTB5102G005076
SCDMTB5192G004573	SCDMTB5192G004623	SCDMTB5122G004673	SCDMTB5142G004741	SCDMTB5122G005015	SCDMTB5122G005077
SCDMTB5102G004574	SCDMTB5102G004624	SCDMTB5142G004691	SCDMTB5182G004742	SCDMTB5142G005016	SCDMTB5162G005082
SCDMTB5122G004575	SCDMTB5122G004625	SCDMTB5162G004692	SCDMTB5182G004743	SCDMTB5152G005017	SCDMTB5182G005083
SCDMTB5142G004576	SCDMTB5142G004626	SCDMTB5182G004693	SCDMTB51X2G004744	SCDMTB5182G005018	SCDMTB51X2G005084
SCDMTB5162G004577	SCDMTB5162G004627	SCDMTB51X2G004694	SCDMTB5112G004745	SCDMTB51X2G005019	SCDMTB5112G005085
SCDMTB5182G004578	SCDMTB5182G004628	SCDMTB5112G004695	SCDMTB5132G004746	SCDMTB5162G005020	SCDMTB5132G005086

SCDMTB5192G005089	SCDMTB5132G005153	SCDMTB5102G005207	SCDMTB5142G005260	SCDMTB5102G005515	SCDMTB5112G005586
SCDMTB5152G005090	SCDMTB5152G005154	SCDMTB5122G005208	SCDMTB5162G005261	SCDMTB5122G005516	SCDMTB5132G005587
SCDMTB5172G005091	SCDMTB5172G005155	SCDMTB5102G005210	SCDMTB5182G005262	SCDMTB5142G005517	SCDMTB5152G005588
SCDMTB5192G005092	SCDMTB5192G005156	SCDMTB5122G005211	SCDMTB5162G005263	SCDMTB5162G005518	SCDMTB5172G005592
SCDMTB5142G005095	SCDMTB5102G005157	SCDMTB5142G005212	SCDMTB5112G005264	SCDMTB5182G005522	SCDMTB5192G005593
SCDMTB5162G005096	SCDMTB5122G005158	SCDMTB5162G005213	SCDMTB5132G005265	SCDMTB5152G005523	SCDMTB5102G005594
SCDMTB5182G005097	SCDMTB5142G005159	SCDMTB5182G005214	SCDMTB5152G005266	SCDMTB5112G005524	SCDMTB5122G005595
SCDMTB51X2G005098	SCDMTB5102G005160	SCDMTB51X2G005215	SCDMTB5172G005267	SCDMTB5132G005525	SCDMTB5142G005596
SCDMTB5132G005103	SCDMTB5122G005161	SCDMTB5112G005216	SCDMTB5192G005268	SCDMTB5152G005526	SCDMTB5182G005603
SCDMTB5152G005106	SCDMTB5142G005162	SCDMTB5132G005217	SCDMTB5102G005269	SCDMTB5172G005527	SCDMTB51X2G005604
SCDMTB5172G005107	SCDMTB5152G005163	SCDMTB5152G005218	SCDMTB5172G005270	SCDMTB5192G005528	SCDMTB5112G005605
SCDMTB5192G005108	SCDMTB5182G005164	SCDMTB5172G005219	SCDMTB5192G005271	SCDMTB5102G005529	SCDMTB5132G005606
SCDMTB5102G005109	SCDMTB51X2G005165	SCDMTB5152G005221	SCDMTB5102G005272	SCDMTB5172G005530	SCDMTB5152G005607
SCDMTB5172G005110	SCDMTB5112G005166	SCDMTB5172G005222	SCDMTB5122G005273	SCDMTB5192G005531	SCDMTB5172G005608
SCDMTB5192G005111	SCDMTB5132G005167	SCDMTB5192G005223	SCDMTB5142G005274	SCDMTB5102G005532	SCDMTB5192G005609
SCDMTB5102G005112	SCDMTB5152G005168	SCDMTB5102G005224	SCDMTB5112G005276	SCDMTB5122G005533	SCDMTB5152G005610
SCDMTB5142G005114	SCDMTB5172G005169	SCDMTB5122G005225	SCDMTB5132G005279	SCDMTB5142G005534	SCDMTB5172G005611
SCDMTB5182G005116	SCDMTB5132G005170	SCDMTB5142G005226	SCDMTB5112G005280	SCDMTB5162G005535	SCDMTB51X2G005618
SCDMTB51X2G005117	SCDMTB5152G005171	SCDMTB5162G005227	SCDMTB5112G005281	SCDMTB5182G005536	SCDMTB5112G005619
SCDMTB5112G005118	SCDMTB5172G005172	SCDMTB5182G005228	SCDMTB5132G005282	SCDMTB51X2G005537	SCDMTB5182G005620
SCDMTB5132G005119	SCDMTB5192G005173	SCDMTB51X2G005229	SCDMTB5152G005283	SCDMTB5172G005544	SCDMTB51X2G005621
SCDMTB51X2G005120	SCDMTB5102G005174	SCDMTB5162G005230	SCDMTB5172G005284	SCDMTB5192G005545	SCDMTB5112G005622
SCDMTB5112G005121	SCDMTB5122G005175	SCDMTB5182G005231	SCDMTB5192G005285	SCDMTB5102G005546	SCDMTB5132G005623
SCDMTB5132G005122	SCDMTB5162G005177	SCDMTB51X2G005232	SCDMTB5102G015286	SCDMTB5122G005547	SCDMTB5152G005624
SCDMTB5152G005123	SCDMTB5182G005178	SCDMTB5112G005233	SCDMTB5122G005287	SCDMTB5142G005548	SCDMTB5172G005625
SCDMTB5172G005124	SCDMTB51X2G005179	SCDMTB5132G005234	SCDMTB5142G005288	SCDMTB5162G005549	SCDMTB5192G005626
SCDMTB5192G005125	SCDMTB5182G005181	SCDMTB5152G005235	SCDMTB5162G005289	SCDMTB5122G005550	SCDMTB5102G005627
SCDMTB5102G005126	SCDMTB51X2G005182	SCDMTB5172G005236	SCDMTB5122G005290	SCDMTB5112G005555	SCDMTB5122G005628
SCDMTB5122G005127	SCDMTB5112G005183	SCDMTB5192G005237	SCDMTB5142G005291	SCDMTB5132G005556	SCDMTB5102G005630
SCDMTB5142G005128	SCDMTB5132G005184	SCDMTB5102G015238	SCDMTB5152G005292	SCDMTB5152G005557	SCDMTB5122G005631
SCDMTB5122G005130	SCDMTB5152G005185	SCDMTB5122G005239	SCDMTB5112G005295	SCDMTB5172G005558	SCDMTB5142G005632
SCDMTB5142G005131	SCDMTB5172G005186	SCDMTB5192G005240	SCDMTB5132G005296	SCDMTB5192G005559	SCDMTB5162G005633
SCDMTB5162G005132	SCDMTB5192G005187	SCDMTB5102G005241	SCDMTB5152G005297	SCDMTB5152G005560	SCDMTB5182G005634
SCDMTB51X2G005134	SCDMTB5102G005188	SCDMTB5142G005243	SCDMTB5172G005298	SCDMTB5172G005561	SCDMTB5112G005635
SCDMTB5112G005135	SCDMTB5122G005189	SCDMTB5162G005244	SCDMTB5192G005299	SCDMTB5192G005562	SCDMTB5112G005636
SCDMTB5132G005136	SCDMTB5102G005191	SCDMTB5182G005245	SCDMTB5112G005300	SCDMTB5102G005563	SCDMTB5132G005637
SCDMTB5152G005137	SCDMTB5122G005192	SCDMTB51X2G005246	SCDMTB5102G005308	SCDMTB5122G005564	SCDMTB5132G005640
SCDMTB5172G005138	SCDMTB5142G005193	SCDMTB51X2G005247	SCDMTB5102G005501	SCDMTB5142G005565	SCDMTB5152G005641
SCDMTB5192G005139	SCDMTB5162G005194	SCDMTB5132G005248	SCDMTB5122G005502	SCDMTB5162G005566	SCDMTB5172G005642
SCDMTB5152G005140	SCDMTB51D2G005196	SCDMTB5152G005249	SCDMTB5142G005503	SCDMTB5152G005567	SCDMTB5192G005643
SCDMTB5192G005142	SCDMTB5112G005197	SCDMTB5112G005250	SCDMTB5162G005504	SCDMTB51X2G005568	SCDMTB5102G005644
SCDMTB5102G005143	SCDMTB5132G005198	SCDMTB5132G005251	SCDMTB5182G005505	SCDMTB5112G005569	SCDMTB5122G005645
SCDMTB5122G005144	SCDMTB5152G005199	SCDMTB5152G005252	SCDMTB51X2G005506	SCDMTB5182G005570	SCDMTB5142G005646
SCDMTB5142G005145	SCDMTB5182G005200	SCDMTB5172G005253	SCDMTB5112G005507	SCDMTB51X2G005571	SCDMTB5162G005647
SCDMTB5162G005146	SCDMTB51X2G005201	SCDMTB5192G005254	SCDMTB5132G005508	SCDMTB5192G005576	SCDMTB5182G005648
SCDMTB5182G005147	SCDMTB5112G005202	SCDMTB5102G005255	SCDMTB5152G005509	SCDMTB5102G005577	SCDMTB51X2G005649
SCDMTB51X2G005148	SCDMTB5132G005203	SCDMTB5122G005256	SCDMTB5112G005510	SCDMTB5122G005578	SCDMTB5162G005650
SCDMTB5112G005149	SCDMTB5152G005204	SCDMTB5142G005257	SCDMTB5132G005511	SCDMTB5142G005579	SCDMTB5182G005651
SCDMTB5182G005150	SCDMTB5172G005205	SCDMTB5162G005258	SCDMTB5152G005512	SCDMTB5182G005584	SCDMTB51X2G005652
SCDMTB51X2G005151	SCDMTB5192G005206	SCDMTB5182G005259	SCDMTB5192G005514	SCDMTB51X2G005585	SCDMTB5132G005654

SCDMTB5152G005655	SCDMTB5162G005681	SCDMTB5102G005711	SCDMTB5152G007101	SCDMTB51X2G007126	SCDMTB5149G009739
SCDMTB5172G005656	SCDMTB5182G005682	SCDMTB5122G005712	SCDMTB5172G007102	SCDMTB5112G007127	SCDMTB5103G009740
SCDMTB5192G005657	SCDMTB51X2G005683	SCDMTB5142G005713	SCDMTB5192G007103	SCDMTB5132G007128	SCDMTB5123G009741
SCDMTB5102G005658	SCDMTB5112G005684	SCDMTB5162G005714	SCDMTB5102G007104	SCDMTB5152G007129	SCDMTB5163G009743
SCDMTB5122G005659	SCDMTB5132G005685	SCDMTB5182G005715	SCDMTB5122G007105	SCDMTB5112G007130	SCDMTB5183G009744
SCDMTB5192G005660	SCDMTB5152G005686	SCDMTB51X2G005716	SCDMTB5142G007106	SCDMTB5132G007131	SCDMTB51X3G009745
SCDMTB5102G005661	SCDMTB5172G005687	SCDMTB5112G005717	SCDMTB5162G007107	SCDMTB5152G007132	SCDMTB5113G009746
SCDMTB5122G005662	SCDMTB5192G005688	SCDMTB5132G005718	SCDMTB5182G007108	SCDMTB5172G007133	SCDMTB5153G009748
SCDMTB5142G005663	SCDMTB5102G005689	SCDMTB5152G005719	SCDMTB51X2G007109	SCDMTB5192G007134	SCDMTB5153G009751
SCDMTB5162G005664	SCDMTB5122G005693	SCDMTB5112G005720	SCDMTB5162G007110	SCDMTB5182G007142	SCDMTB5173G009752
SCDMTB5182G005665	SCDMTB5142G005694	SCDMTB5132G005721	SCDMTB5182G007111	SCDMTB5152G007146	Scout 2003
SCDMTB51X2G005666	SCDMTB5162G005695	SCDMTB5152G005722	SCDMTB51X2G007112	SCDMTB5172G007147	SCDMTB5103G009761
SCDMTB5112G005667	SCDMTB5182G005696	SCDMTB5172G005723	SCDMTB5112G007113	SCDMTB5192G007148	SCDMTB5113G009767
SCDMTB5132G005668	SCDMTB51X2G005697	SCDMTB5192G005724	SCDMTB5132G007114	SCDMTB5102G007149	SCDMTB5123G009759
SCDMTB5152G005669	SCDMTB5112G005698	SCDMTB5102G005725	SCDMTB5152G007115	SCDMTB5172G007150	SCDMTB5123G009762
SCDMTB5112G005670	SCDMTB5132G005699	SCDMTB5122G005726	SCDMTB5172G007116	SCDMTB5192G007151	SCDMTB5133G009768
SCDMTB5132G005671	SCDMTB51X2G005702	SCDMTB5142G005727	SCDMTB5192G007117	SCDMTB5102G007152	SCDMTB5143G009763
SCDMTB5152G005672	SCDMTB5112G005703	SCDMTB5162G005728	SCDMTB5102G007118	SCDMTB5122G007153	SCDMTB5153G009769
SCDMTB5172G005673	SCDMTB5132G005704	SCDMTB5182G005729	SCDMTB5122G007119	SCDMTB5142G007154	SCDMTB5153G009772
SCDMTB5192G005674	SCDMTB5152G005705	SCDMTB5142G005730	SCDMTB5192G007120	SCDMTB5162G007155	SCDMTB5163G009764
SCDMTB5102G005675	SCDMTB5172G005706	SCDMTB5162G005731	SCDMTB5102G007121	SCDMTB5182G007156	SCDMTB5173G009773
SCDMTB5122G005676	SCDMTB5192G005707	SCDMTB5182G005732	SCDMTB5122G007122	SCDMTB51X2G007157	SCDMTB5183G009765
SCDMTB5142G005677	SCDMTB5102G005708	SCDMTB51X2G005733	SCDMTB5142G007123	Spirit 2003	
SCDMTB5182G005679	SCDMTB5122G005709	SCDMTB5112G005734	SCDMTB5163G007124	SCDMTB5133G009425	
SCDMTB5142G005680	SCDMTB5192G005710	SCDMTB5132G005735	SCDMTB5182G007125	SCDMTB5103G009429	



April ___, 2003

Dear Indian Motorcycle Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Any vehicle lessor who receives this notice must forward a copy to the lessee within 10 days, as required by Federal law.

REASON FOR NOTICE

Indian Motorcycle Corporation ("IMC") has decided that a defect which relates to motor vehicle safety exists in certain 2002 and 2003 Indian Spirit™ and Scout™ motorcycles produced through September 4, 2002. Due to the positioning of the gas tank vent tube, the vent tube can become clogged with debris, particularly in wet weather. Vent tube clogging can cause interruption of fuel flow to the carburetor, causing the bike to come to a halt. A clogged vent tube may also cause pressure to build up in the gas tank and push a small amount of gas out of the fuel filter cap seal.

WHAT YOUR INDIAN DEALER WILL DO

Your dealer will replace your current vent tube with a longer tube repositioned to prevent clogging. This replacement will be performed without charge to you. If you have previously had your vent tube replaced, please contact IMC Customer Service at the number given below to obtain a reimbursement.

WHAT YOU SHOULD DO

Your IMC dealer is fully prepared to assist you. Please contact your IMC dealer as soon as possible to arrange a service date so the dealer may repair your bike. The actual labor time necessary to replace the vent tube is around 20 minutes, but your dealer may need additional time with your motorcycle depending on how appointments are scheduled and processed. When you make your appointment with the dealer, please let the dealer know that you are coming in for the recall work so that the dealer can order the necessary replacement parts.

If you need assistance locating the IMC dealer or authorized service center nearest you, please contact IMC Customer Service at 1-888-899-2997. Also, if you take your bike in on an agreed service date and the repair is not performed within a reasonable time, please call IMC Customer Service. If you have sold or traded your bike, please let us know by completing the postage paid reply card and returning it to us.

If after contacting your dealer and IMC customer service you still have not received the necessary service without charge within a reasonable amount of time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S. W., Washington, D.C. 20590 or call 1-888-327-4236.

We here at IMC apologize for any inconvenience this has caused you. Please understand that we have sent you this notice because we care about your safety. We urge you to get your bike serviced promptly.

Thank you for your attention to this important matter.

George Nobile, Vice President of Customer Service

200 EAST TENTH ST. • GILROY, CALIFORNIA • U. S. A. 95020
TEL: (408) 846-7228 • FAX: (408) 847-3902